


SERVICE INFORMATION

Phased out Ball valves , New male coupling design, Phoenix Fault safety

Phased out Ball valves

Due to decreased sales of ball valves in brass, the following parts are being phased out and replaced by the following:

Old item no	Description	New item no	Description
669210	Low pressure valve w/vulc. coupling, brass	668210	Low pressure valve w/vulc. coupling, stainless steel
669200	Low pressure valve, brass	668200	Low pressure valve, stainless steel
669100	Ball valve, brass	669110	Ball valve, stainless steel



New male coupling design

Our 1/2" male coupling, item number 641700 has been re-designed.

Now it is possible to tighten the coupling, using only a 10mm Allen Key key.



Phoenix fault safety

At the Mixstation – MIX08 and MIX20 - The inlet valve has been upgraded to a spring return version plus the overflow switch has been inverted to a fault safe mode. This is adding safety to the unit and setting down the risk of breakdown and accidental use.

Should you need any further information do not hesitate to contact our company.

For further
information
please contact :

Nilfisk FOODs sales department
on: dir. tel: +45 2969 5100 or
send a request to our info mail:
info@nilfiskfood.com